NAVY Declassification/Release Instructions on Approved For Release 2003/19/94f; CIA-RDP,80-00809A000500630155-8 File CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

25X1A INFORMATION REPORT SUBJECT Poti/Port Facilities and Requirements/Water Depth DATE DISTR. 24 Sep 1954 NO. OF PAGES THE UNITED STATES WITHIN THE MEANING OF TITLE IS SECTIONS

NO. OF ENCLS.

SUPP. TO

REPORT NO.

25X1A

DATE ACQUIRED (BY SOURCE)

DATE (OF INFO.)

PLACE ACQUIRED (BY SOURCE)

COUNTRY USSR

OF THE U.S. COUL. AS AMENDED. ITS TRANSMISSION OF REV ON UP ITS CONTENTS TO OR RICLEPT BY AN UNAUTHURIZED FURSON AND THE REPRESENCTION OF THIS PARRAL IS CHRISTIT

THIS IS UNEVALUATED INFORMATION

US merchant ship master, presumably reliable.

SOURCE

He found the following information in his own ship to voyage reports prepared for future use of other merchant ship masters. He helicves the information is quite accurate as of the date indicated March 1943. The Navy's interviewing officer rates the information as probably true.

The Office of Naval Intelligence furnished the following information to CIA for LAC dissemination in accordance with paragraph 3(c), NSCID 7. (DIO-11ND Conf report No 371-541/

- Entrance Instructions: on a course 1170 true. The approach to Poti is best from the West/Northwest to a course 1170 true. breakwater. A northerly set must be guarded against, as it may set the vessel on a choal. There are no mine fields cutside of Poti. Pilotage is compulsory, and the pilot will meet the vessel about 1 miles outside the breakwater.
- 2. Documents Required: The following documents are required: Bills of Health, Ship's Register, Ship's Articles, Manifest of Cargo, and Crew List. The ship's agent makes up a set of Crew Lists in Russian.
- 3. Agents: The ship's agents were "Inflot". They were of very little help except as interpreters. They speak very little English.
- 4. Security Procedure: About the same procedure that is used today in Russian ports was enforced. A two to three-hour search was conducted prior to entering and leaving port.
- 5. Manyarese Dock: The Manganese Dock has only 23 feet of water alongside. It is customary to load to 23 feet and then to breast the vessel off the dock about 15 Feet to complete loading. Maximum draft at Poti is 20 feet, and then the wessel was in the mud most of the time.
- 6. Cargo Handling: Ore is loaded with cranes at a rate of about 150-200 tons per hour around the clock. The ship's crew must take off and replace the hatches and strong backs both on deck and between decks. There was no pillerage.
- 7. Purst There are two medium-sized tugs at Poti.
- 8. Repairs: Small repairs may be made it absolutely necessary.
- Supplies: Fresh water is piped to the wharves and is plentiful. No other supplies are available.

U.S. Officials Only

COMP IDENTIAL

			#11				
STATE MONTHESTATE	AAMI	34 V 1	1	FB!			
This report is for	the use within t	be USA of th	10 11 1 11 1 12	20. 0.3033000	——————————————————————————————————————	20. 23020 00000 000	
Agencies indicated	above. It is no	t to be true	18001177 9	or some with our	the e	ie Departments	or
originating office t	hrough the Assist	ant Director	of the Co.	of Collection	and t	Meenmination of	(1)1.

Approved For Release 2003/10/01	: CIA-RDP80-00809A000500630155-8 2
---------------------------------	------------------------------------

CONFIDENTIAL/US OFFICIALS OMY

- 2 -

10. Passage Through Dardanelles and Bosporus:

- a. Pilots: Pilotage is not compulsory but is advisable due to the currents and frequent low visability. The signal for the pilot is two long and one short blast on the whistle. He may be called day or night.
- b. Black Sea Pilot:
 often erroneous.
 Dardanelles and Bosporus must proceed at slow speeds, while actually all ships proceed at full speed.
- c. <u>Navigational Aids</u>: The aids to mavigation at both entrances are good, if the visibility is good. In the Dardanelles and the Bosporus, navigational aids are poor and unreliable.
- d. Quarantine Procedure: Vessels bound from the Aegean Sca to the Black Sea must stop at Chanok, in the Dardanelles, for quarantine. Vessels bound from the Black Sea must stop at Buyudere. The doctors seldom board the vessel. Usually the Ship's Register, Crew List, and Bills of Health are taken down to the doctor's boat.

·· and ··

THE MARK GOVERN AND AREA WITHOUT WITH

750.547 318 **7** 750.547 318 **7** 750.547 318 750.548 318

CONFIDENTIAL/US OFFICIALS ONLY